## BY ORDER OF THE COMMANDER 56TH FIGHTER WING (AETC)



## AIR FORCE INSTRUCTION 11-301 VOLUME 1

AIR EDUCATION AND TRAINING
COMMAND
Supplement

LUKE AIR FORCE BASE Supplement 6 DECEMBER 2011

Flying Operations

AIRCREW FLIGHT EQUIPMENT (AFE)
PROGRAM

#### COMPLIANCE WITH THIS PUBLICATION IS MANDATORY

ACCESSIBILITY: Publications and forms are available on the e-Publishing website at

www.e-Publishing.af.mil for downloading or ordering.

**RELEASABILITY:** There are no releasability restrictions on this publication.

OPR: 56 OSS/OSL
Supersedes: AFI11-301\_LUKEAFBSUP
Certified by: 56 OG/CC
(Col Douglas R. Miller)

1, 28 January 2010 Pages: 19

This supplement implements and extends the guidance of Air Force Instruction (AFI) 11-301, Volume 1, Aircrew Flight Equipment (AFE) Program, 25 February 2009 and AFI 11-301, Volume 1 Aircrew Flight Equipment (AFE) Program, Air Education and Training Command Supplement 1, 18 August 2009. It establishes the 56th Fighter Wing (56 FW) Aircrew Flight Equipment (AFE) program. This supplement does not apply to Air Force Reserve Command (AFRC) and to Air National Guard (ANG) Units. It applies to 56 FW Pilots who fly in aircraft assigned to the 56 FW and all AFE personnel. Refer recommended changes and questions about this publication to the Office of Primary Responsibility (OPR) using the AF Form 847, Recommendation for Change of Publication; route AF Forms 847 from the field through the appropriate functional's chain of command. Ensure that all records created as a result of processes prescribed in this publication are maintained in accordance with Air Force Manual (AFMAN)

33-363, Management of Records, and disposed of in accordance with Air Force Records Information Management System (AFRIMS) Records Disposition Schedule (RDS) located at https://www.my.af.mil/gcss-af61a/afrims/afrims/rds\_series.cfm

#### SUMMARY OF CHANGES

This document has been substantially revised and must be completely reviewed. Major changes include establishing local procedures for AFE Superintendent access to SIPR account access (paragraph 1.4.6.1); deletes the requirement for AFE personnel to have access to the 56 OSS/OSL CoP (1.4.7); specifies members of the wing Exercise Evaluation Team (EET) (paragraph 2.10.3); specifies requirements for each satellite AFE section to have a Cost Per Flying Hour (CPFH) government purchase cardholder (paragraph 2.10.7); standardizes 56 FW Advanced Concept Ejection Seat (ACES) configurations (2.10.9); identifies approved waiver for AFECT Emergency Egress Training granted by HQ USAF/A3O (2.10.14.2); identifies requirement for AFE Quality Assurance Evaluators (QAE) to maintain training records (paragraph, 2.11.21); deleted requirement for use of ALERTS for QA program management (paragraph, 2.12.1.1); reduced the number of QA special inspections, personnel evaluations and quality verification inspections required each month (paragraphs 2.12.12.1, 2.12.12.2, 2.12.12.3), deleted requirement to use Tool Accountability System for Composite Tool Kits (paragraph 3.8.1), deleted requirement for third-party certification for all training tasks (paragraph, 4.1.2.2), Added requirement for section NCOICs to send training stats to AFE Training (paragraph, 4.2.2.11)

- 1.3.2. 56 OG/CC is the overall waiver authority for this supplement. Squadron Commanders will route waiver requests through the 56 OSS/OSL AFE Officer/Superintendent (AFEO/S) and 56 OSS/CC for approval. All higher headquarters waiver requests will be routed in accordance with the guidance provided in the parent AFI and MAJCOM supplements.
- 1.4.2. Only the AFEO/S will contact HQ AETC/A3OL directly.
- 1.4.6.1. The AFES will maintain a SIPR account for classified communications. Access to this account will be provided by the 56 OG/OGI Intelligence section. Coordination for access to the Intelligence facility will be coordinated through the 56 OG/OGI Superintendent at x9019.
- 2.9.25. The 56 OG/CC will program funds into the operational and maintenance budget for the AFE MAJCOM Functional Manager to visit the 56 OSS/OSL function at least once every two years.
- 2.10.2. The primary appointed AFE Quality Assurance (QA) inspector will report directly to the AFEO/S for functional guidance. If available, a highly qualified 1P071 will be appointed to assist the primary QA inspector.
- 2.10.2.1. The primary AFE QA inspector will be rotated every 24 months. If available, the secondary QA inspector will be appointed for a minimum of 6 months.
- 2.10.3. The AFES, primary AFE QA inspector and Flight Chief will all be assigned as members of the wing EET.
- 2.10.7. At a minimum, each satellite AFE section will have a CPFH government purchase cardholder.
- 2.10.8. 56 FW AFE personnel may be used for duties outside of their functional expertise (ie., UDM, ESOH, Base Honor Guard) for a period not to exceed 365 days. If at any time the 56 FW AFE manning drops below 90% assigned versus authorized personnel, all personnel assigned to external duties will be reassigned to the AFE flight. All AFE personnel tasked for non-AFE

related duties lasting greater than five duty days will be coordinated through the 56 OG/CCC and the AFEO/S.

- 2.10.9. 56 FW Advanced Concept Ejection System II (ACES) survival kits will be configured with the items listed in Attachment 4 of this supplement.
- 2.10.14.2. HQ USAF/A3O-AT has granted the 56 FW enlisted AFECT instructors the authority to teach LL02-Emergency Egress, Ejection Seat Training in lieu of rated pilots. This waiver has been granted until the next rewrite of the basic publication unless revoked sooner by the granting authority. A copy of this waiver will be maintained in the 56 OSS/OSL ERM folder and the AFECT continuity binder.
- 2.11.3. 56 FW AFE will have one TODO, who will ensure each AFE section has a current file of publications and TOs. All AFE technicians will check and sign off read files weekly, as required. Section NCOICs will ensure all assigned technicians are familiar with all TOs pertaining to the equipment within their section. The TO, Message, and Read Fam files are located on the OSS/OSL DFS drive.
- 2.11.4. All AFE sections will utilize digital TOs to the maximum extent possible. Paper copy TOs will be maintained IAW TO 00-5-1. "For Reference Use Only" TOs will not be used for maintaining AFE.
- 2.11.21. AFE SNCOs assigned as AFE QA Evaluators will maintain training records.
- 2.11.22. All AFE SNCOs, AFE QA, and parachute/kit section NCOICs will subscribe to receive automated updates to the 784th Combat Sustainment Group Conventional Munitions Restricted Suspended listing.
- 2.12.2. No-notice inspections will be documented on an AF Form 2420, Quality Control Inspection Summary, or equivalent. Results of no-notice QA inspections will be posted in the QA folder in the OSS/OSL Common folder. Section NCOICs will post corrective actions for open discrepancies within one week of discovery date. Discrepancies will be corrected and annotated with TO or instruction reference for corrective action.
- 2.12.3. Monthly, section NCOICs or designated representative will track positive, negative, individual and shop trends utilizing QCI data from the AF form 2420s in the shop QA binder; any identifiable trend (three or more; shop or individual) will be annotated. NCOICs or designated representative will also compile a trend analysis report, Attachment 6 (Added), to summarize the month's trends. NCOICs will ensure the trend analysis report and the AF Form 2420s are documented and reviewed by all technicians. Maintain trend analysis data in a separate binder with a tab for each month of the year. Trend/QCI data and trend analysis reports will be filed within five duty days of the first day of each month and kept on file for 12 months.
- 2.12.3.1. (Added) If a technician continues to repeat a specific discrepancy for two consecutive months, the section NCOIC will provide the technician with feedback and additional training, if required. NCOICs will also document feedback/training provided in the technician's training record (TBA Journal Entry) and with a Memorandum for Record (MFR.) The MFR will be maintained for 12 months.
- 2.12.3.2. (Added) Monthly trend analysis data will be provided to the 56 OSS/CC using the 56 OSS/OSL QA slide show. AFE QA will provide this product to the 56 OSS AFES no later than the 5th duty day of each month.

2.12.6. AFE QA section will evaluate first article produced for all TCTOs to ensure proper compliance and ensure coordination through MXG/QA and 56 FW Plans and Scheduling, as required. QA will document acceptance of first article inspections on locally developed TCTO tracking sheets.

2.12.8.

Section N COICs will use the following approved IPI/CPI checklists:

- 2.12.8.1. (Added) ACES II Survival Kit, Attachment 7 (Added)
- 2.12.8.2. (Added) ACES II Parachute, Attachment 8 (Added)
- 2.12.8.3. (Added) Drogue Chute, Attachment 9 (Added)
- 2.12.8. 4 (Added) LPU-38/P, Attachment 10 (Added)
- 2.12.10.

Section N COICs will maintain a copy of all approved locally designed tools in their respective CTK binders. Master copies will be maintained by the AFE QA office.

- 2.12.12. (Added) The AFE QA section will accomplish the following inspections on a monthly basis:
- 2.12.12.1. (Added) Special Inspections will be conducted on AFE programs and general housekeeping procedures. QA Inspectors will complete a minimum of 18 special inspections per month.
- 2.12.12.2. (Added) Personnel Evaluation inspections will consist of individuals performing a specific task. QA Inspectors will conduct a minimum of 10 personnel evaluations per month.
- 2.12.12.3. (Added) Quality Verification Inspections will provide final inspection on equipment that is task completed (finished product). QA Inspectors will perform a minimum of 14 quality verification inspections per month.
- 2.12.13. (Added)

Section Q uality Control Binders will be set-up as follows (section NCOICs are authorized to omit tabs that do not pertain to their section):

- 2.12.13.1. (Added) Tab A- Quality Control Inspector Appointment Letter
- 2.12.13.2. (Added) Tab B- Helmets/Masks
- 2.12.13.3. (Added) Tab C- Torso Harnesses
- 2.12.13.4. (Added) Tab D- G-Suits
- 2.12.13.5. (Added) Tab E- ACES II Survival Kits
- 2.12.13.6. (Added) Tab F- ACES II Parachutes/Drogue Parachutes/Drag Parachutes
- 2.12.13.7. (Added) Tab G- Life Preservers
- 2.12.13.8. (Added) Tab H- Night Vision Goggles
- 2.12.13.9. (Added) Tab I- Anti-Exposure Suits
- 2.12.13.10. (Added) Tab J- Oxygen Connectors

- 2.12.13.11. (Added) Tab K- Pre/Postflight Inspections
- 2.12.13.12. (Added) Tab L- Outside Agencies
- 2.13.3. 56 OSS/OSL annual program assessment will be conducted no later than 30 April. Results will be forwarded to the 56 OG/CC for approval via electronic Staff Summary Sheet with an executive summary of findings. Approved results will be forwarded to all 56 FW flying squadron commanders.
- 2.14.5. (Added) Pilots will PCS with only their Joint Helmet Mounted Cueing System visor. Deviations to this policy will be coordinated with the AFES.
- 2.15.11.2. (Added) Local manufacture requests are approved only for technical directed or items source maintenance recovery (SMR) coded as local manufacture only. Contact the LRS Local Manufacture Supply point for assistance.
- 2.15.11.3. (Added) All requests for local manufacture must be approved by the Aircrew Flight Equipment Section Chief or designated representative(s). Requests must be accompanied with a sample item (preferred) or technical drawing. The local manufacturing section personnel will help in determining local manufacturing requirements as needed.
- 2.15.11.4. (Added) Once approved, all pieces/parts will be ordered by the requesting activity and delivered once all items are in hand to the manufacturing activity.
- 2.15.11.5. (Added) Local manufactured items will be completed in order of receipt and as soon as mission and manning allows.

2.15.19.

Section N COICs will conduct a self-assessment of their section within 30 days of being appointed as NCOIC and annually thereafter.

- 2.18.2.1. Helmet Mounted Device (HMD) Section NCOIC will coordinate with the Optometry clinic for annual eye exams for all NVG maintainers in March of each year. Documentation of this eye exam will be maintained in the HMD section as well as the member's AF Form 55, Employee Safety and Health Record.
- 3.7.6. An AF IMT 2420 will be used to document QCIs.
- 3.8.1.1. (Added)

Section C TK Monitors will follow the 56 FW routing and procedure checklist, AETC Form 138, Lost Tool or Item Investigation Record, any time a tool is lost.

- 3.8.1.2. Sections will utilize hardcopy sign in/out procedures. These procedures will include:
- 3.8.1.2.1. (Added) Documenting daily Opening/Closing inventory against the current MIL on AETC Form 1042, *CTK/Tool Checklist*.
- 3.8.1.2.2. (Added) Documenting lost or missing tools on an AF IMT 3131, *Missing/Removed Tools and Equipment Log*.
- 3.8.1.2.3. (Added) Documenting 90-Day Inspections and Annual Inspections on an AF Form 2411, *Inspection Document*.
- 3.12.1. Due to the lack of controlled munitions or weapons, 56 FW AFE sections are not required to have a resource protection Operating Instruction. All AFE technicians will ensure

pilferable items are secured in locked containers when not under the direct control of AFE personnel.

- 3.13.6. (Added) Cell phone use is not permitted in any section where maintenance of equipment is performed.
- 4.1.2.4. (Added) Supervisors/Trainers will document training progress using TBA Journal Entries, using the following intervals:
- 4.1.2.4.1. (Added) Monthly for technicians in Upgrade Training (UGT).
- 4.1.2.4.2. (Added) Quarterly for all others.
- 4.2.2.11. (Added) AFE section NCOICs will ensure updated training stats are sent to the AFE Training Section weekly for personnel in upgrade training and no later than the last Wednesday of the month for all others.
- 5.8.5. AFE is not responsible for updating pilot training in the Graduate Training Integrated Management System (GTIMS.)
- 5.9.4. AFECTs will update training equipment inspections using Flight Equipment Records Management System.

JERRY D. HARRIS, JR. Brigadier General, USAF Commander

#### **Attachment 1**

#### GLOSSARY OF REFERENCES AND SUPPORTING INFORMATION

#### References

AFI 11-301 Volume 1, Aircrew Flight Equipment (AFE) Program, 25 February 2009

AFI 11-301 Volume 1, Air Education and Training Command Supplement, *Aircrew Flight Equipment (AFE) Program,* 18 Aug 2009

AFMAN 33-363, Management of Records, 1 March 2008

Technical Order 00-5-1, AF Technical Order System, 1 May 2011

#### Adopted Forms

AETC Form 138, Lost Tool or Item Investigation Record

AETC Form 1042, CTK/Tool Checklist

AF Form 2411, Inspection Document

AF Form 2420, Quality Control Inspection Summary

AF IMT 3131, Missing/Removed Tools and Equipment Log

AF Form 55, Employee Safety and Health Record.

AF Form 847, Recommendation for Change of Publication

#### Abbreviations and Acronyms

**ACES**— Advanced Concept Ejection System

**AFE**— Aircrew Flight Equipment

**AFECT**— Aircrew Flight Equipment Continuation Training

**AFI**— Air Force Instruction

**AFMAN**—Air Force Manual

**AFEO**— Aircrew Flight Equipment Officer

**AFES**— Aircrew Flight Equipment Superintendent

**ALERTS**— Automated Life Sustaining Equipment Records Tracking System

**AFRC**— Air Force Reserve Command

ANG— Air National Guard

**CC**— Commander

**CoP**— Community of Practice

**CPFH**— Cost Per Flying Hour

**CPI**— Critical Points Inspection

CTK— Composite Tool Kit

**EET**— Exercise Evaluation Team

**ERM**— Electronics Records Management

**ESOH**— Environmental Safety and Occupational Health

**FW**— Fighter Wing

**GTIMS**— Graduate Training Integration Management System

**HMD**— Helmet Mounted Device

IAW— In Accordance With

**IPI**— In-Process Inspection

**LPU**— Life Preserver Unit

**LRS**— Logistics Readiness Squadron

**MAJCOM**— Major Command

**MFR**— Memorandum for Record

**MXG**— Maintenance Group

**NCOIC**— Noncommissioned Officer

**NVG**— Night Vision Goggle

**OG**— Operations Group

**OSS**— Operations Support Squadron

**PCS**— Permanent Change of Station

**QA**— Quality Assurance

**QAE**— Quality Assurance Evaluator

**QCI**— Quality Control Inspection

SIPR—Secure Internet Protocol, Routed

**SMR**— Source Maintenance Recovery

**SNCO**— Senior Noncommissioned Officer

**TBA**— Training Business Area

**TCTO**— Time Compliance Technical Order

TO— Technical Order

**TODO**— Technical Order Distribution Office

**UDM**— Unit Deployment Manager

**UGT**— Upgrade Training

### **Attachment 4**

## AIRCREW FLIGHT CLOTHING AND EQUIPMENT REQUIREMENTS

## **A4.2.** (Added)

**Requirements.** Table A4.2 (Added) provides a standard configuration of Advanced Concept Ejection Seat (ACES) II Survival Kits.

56 FW

# Table A4.1. (Added) ACES II Survival Kit Configuration.

## **Auxiliary Container**

Item	Quantity	Remarks
PRC-90-2 W/ Battery Installed	1	Note 1, Note 2
Spare Battery	1	Note 1
Compass	1	
Signal Mirror	1	Note 1
Mk 12/124 Signal Flares	2	Note 1
A/P25S-5A, Personnel Distress	1	Note 1
Kit		
Post-Landing Checklist	1	
Sponge	1	
Whistle	1	

### Main Rucksack

Survival Pamphlet, AFTTP (I) 3-	1	
2.26		
AA Batteries	2	
Combat Blanket	1	
First Aid Kit	1	Note 1, Note 3
Flashlight	1	
Leatherman Tool	1	
Matches w/ Case	1	
Raft Repair Kit	1	
Sea Dye Marker	1	
Sponge	1	
Survival Blanket	1	
Tourniquet	1	Note 1
Water Bottle	1	
Flexpack Water	10	

- **Note 1-** These items will be tied into the survival kit IAW TO14S1-3-51.
- **Note 2-** The radio volume will be set to the max position and marked with white out on the volume control knob for quick reference.
- Note 3- The 56 FW will use only the medical portion of the first aid kit.

**Attachment 6 (Added)** 

#### MONTHLY TREND ANALYSIS FINDINGS



## DEPARTMENT OF THE AIR FORCE 56TH OPERATIONS SUPPORT SQUADRON (AETC) LUKE AIR FORCE BASE ARIZONA

**DATE** 

MEMORANDUM FOR 56 OSS/OSL

FROM: 56 OSS/OSL -- [your squadron] (i.e. 309th AFE)

SUBJECT: TREND ANALYSIS REPORT FOR [month / year]

- 1. The following trends were noted for [month / year].
  - a. Helmets / Masks
- (1) No Trends noted on the helmet. We do need to pay closer attention to the EAL and its condition. Also, note that the Velcro is different between the TPL and Zeta liner.
  - b. Torso Harnesses
- (1) No trends were noted. Pay closer attention to the tacking and signing off the triple nickels on the MS2000.
  - c. G-suits
    - (1) No trends noted.
  - d. ACES II Survival Kits
- (1) Trends were noted on the radio for not turning down the volume, zip lock bags being ripped, and 17 discrepancies for NL 555's not having the proper battery info and not being signed off after inspection. Please pay closer attention to your work. No trends noted.
  - e. ACES II Parachutes (Recovery, Drogue, Drag)
    - (1) Tackings worn and loose.
  - f. LPU-38/P Life preserver

(1) No trends noted.
g. Night Vision Goggles (NVG)
(1) No trends noted.
h. Exposure suits
(1) No trends noted.
i. Oxygen Connectors
(1) No trends noted.
j. Outside Agencies
(1) No trends noted.
2. The following individual trends were noted for [month / year]:
No individual trends were noted for the month
3. Everyone is doing a great job of improving the quality of our equipment. Technicians need to pay closer attention to detail on forms documentation (ALSMS, AFTO 334, AFTO 391 and NL 555). Keep up the good work everyone!
[NCOIC NAME], TSgt, USAF NCOIC, XX FS AFE
Monthly Technician Review (initial below):

## **Attachment 7**

## (ADDED)

Critical Points Inspection / In-process Inspection Checklist

## Table A7.1. (Added) Critical Points Inspection / In-process Inspection Checklist

**Kit Serial Number:** 

**Date Started:** 

## **Date Completed:**

Components	Reference	wuc	CPI/IPI
			Inspector
Radio is inspected and documented on 555?	31R2-2PRC90-1, para 5.10.B	LRA00	
Battery is installed and documented on 555?	31R2-2PRC90-1 para 5-10	LRA19	
Radio is off?	31R2-2PRC90-1 Table 5.1 Step 4	LRA00	
Radio Volume is at highest setting and white out to verify?	Local Policy	LRA00	
Radio antenna marked to verify weight test accomplished?	31R2-2PRC90-1 para 5.38	LRA00	
Radio earpiece superglued and etched with X to verify?	31R2-2PRC90-1 para 5.34 (2)	LRA00	
Beacon inspected and documented on 555?	31R4-2URT44-11 4.6.	91AF0	
Beacon is off?	31R4-2URT44-11 4.1 NOTE	91AF0	
Beacon battery installed?	31R4-2URT44-11 5.4.	91AF0	
Beacon battery cover torque?	31R4-2URT44-11 5.4.5.	91AF0	
BIT test c/w and verified by a 7-Level and their initials?	31R4-2URT44-11 para 5.1.2.	91AF0	
All new/changed components information updated?	14S1-11-3 Para 8.25	SKA99	
All time change items good through next inspection?	14S1-11-3 para 8.24	SKA00	
DOI info marked on cutter?	11P10-6-7 WP 070 section 5	SKA50	
Prefolding Screening	Reference	WUC	CPI/IPI Inspector
Floor and spray shield oral inflation valves open and ¼ turn closed?	14S-102-11 para 7.3 step b	LAR08	
Main tube oral inflation valve closed and locked?	14S-102-11 para 7.3 step c	LAR08	
LRU 16/P Life Raft	Reference	WUC	CPI/IPI Inspector
Raft stenciled initial/365/func and date inspected? DOM:	14S-1-102-11 para 5.5.6	LAR01	

Date of Ingrestion, Initial, 2000.	146 1 103 11 mars F 6	LADO1	
Date of Inspection: Initial: 365D: Functional:	14S-1-102-11 para 5.6	LAR01	
Next Functional due date:	14S-1-102-11 Table 5-6	LAR01	
CO2 cylinder weight checked and initialed?	14S-1-102-11 rable 5-0	LAR06	
Raft sea anchor properly installed?	14S-1-102-11 para 6.8.2	LAR11	
Raft S/N:	14S-1-102-11 Table 5-6	LAR01	
Raft Contract Number:	14S-1-102-11 Table 5-6	LAR01	
Raft folded using method 4?	14S-1-102-11 figure 7-4	LAR01	
Lanyard installed on neck of bottle?	14S1-3-51 para 3-2.3 step g (4)	SKA09	
Universal adapter installed?	14S-1-102-11 para 7.3 step i	LAR06	
Bottle properly Torqued?	14S-1-102-11 para 7.4.1 step i	LAR06	
Swag ball properly attached to bottle?	14S-1-102-11 para 7.4.1 step g	LAR06	
Raft bottle cam at 90 degree angle?	14S-1-102-11 para 7.4 step f	LAR06	
Adapter clip installed correctly?	14S-1-102-11 para 7.4.a step h	LAR06	
Lanyard connected to survival kit and rucksack	14S1-3-51 para 3-2.3 step g	SKA09	
Lanyard safety tied?	14S1-3-51 figure 3-5	SKA09	
All required components installed?	AFI 11-301V1 LAFB Sup table	SKA00	
	A4.1		
1			
Kit Closure	Reference	WUC	CPI/IPI
Kit Closure	Reference	WUC	CPI/IPI Inspector
Cutter actuator lanyard connected, safety tied,	Reference 14S1-11-3 para 5-7	WUC SK08	•
			•
Cutter actuator lanyard connected, safety tied,			•
Cutter actuator lanyard connected, safety tied, and taped?	14S1-11-3 para 5-7	SK08	•
Cutter actuator lanyard connected, safety tied, and taped? Cutter properly installed?	14S1-11-3 para 5-7 14S1-11-3 para 7-2	SK08	•
Cutter actuator lanyard connected, safety tied, and taped? Cutter properly installed? Retaining ring properly installed?	14S1-11-3 para 5-7 14S1-11-3 para 7-2 14S1-11-3 para 7-2	SK08 SKA55 SKA55	•
Cutter actuator lanyard connected, safety tied, and taped? Cutter properly installed? Retaining ring properly installed? Locking cord routed correctly and tacked?	14S1-11-3 para 5-7  14S1-11-3 para 7-2  14S1-11-3 para 7-2  14S1-11-3 para 8-9	SK08  SKA55  SKA55  SKO8	•
Cutter actuator lanyard connected, safety tied, and taped? Cutter properly installed? Retaining ring properly installed? Locking cord routed correctly and tacked? Manual ripcord pin safety tied?	14S1-11-3 para 5-7  14S1-11-3 para 7-2  14S1-11-3 para 7-2  14S1-11-3 para 8-9  14S1-11-3 para 8-11	SK08  SKA55  SKA55  SK08  SKA02	•
Cutter actuator lanyard connected, safety tied, and taped? Cutter properly installed? Retaining ring properly installed? Locking cord routed correctly and tacked? Manual ripcord pin safety tied? Beacon rocker switch installed?	14S1-11-3 para 5-7  14S1-11-3 para 7-2  14S1-11-3 para 7-2  14S1-11-3 para 8-9  14S1-11-3 para 8-11  31R4-2URT44-11 5.2.1 step 6	SK08  SKA55  SKA55  SKA55  SK08  SKA02  SKA41	•
Cutter actuator lanyard connected, safety tied, and taped? Cutter properly installed? Retaining ring properly installed? Locking cord routed correctly and tacked? Manual ripcord pin safety tied? Beacon rocker switch installed? Beacon (URT-44) rocker switch safety pin	14S1-11-3 para 5-7  14S1-11-3 para 7-2  14S1-11-3 para 7-2  14S1-11-3 para 8-9  14S1-11-3 para 8-11  31R4-2URT44-11 5.2.1 step 6	SK08  SKA55  SKA55  SKA55  SK08  SKA02  SKA41	•
Cutter actuator lanyard connected, safety tied, and taped? Cutter properly installed? Retaining ring properly installed? Locking cord routed correctly and tacked? Manual ripcord pin safety tied? Beacon rocker switch installed? Beacon (URT-44) rocker switch safety pin installed?	14S1-11-3 para 5-7  14S1-11-3 para 7-2  14S1-11-3 para 7-2  14S1-11-3 para 8-9  14S1-11-3 para 8-11  31R4-2URT44-11 5.2.1 step 6  31R4-2URT44-11 5.2.1 step 8	SK08  SKA55 SKA55 SK08 SKA02 SKA41 SKA41	•
Cutter actuator lanyard connected, safety tied, and taped? Cutter properly installed? Retaining ring properly installed? Locking cord routed correctly and tacked? Manual ripcord pin safety tied? Beacon rocker switch installed? Beacon (URT-44) rocker switch safety pin installed? Beacon set to 3-BCN (MAJCOM Option)?	14S1-11-3 para 5-7  14S1-11-3 para 7-2  14S1-11-3 para 7-2  14S1-11-3 para 8-9  14S1-11-3 para 8-9  14S1-11-3 para 8-11  31R4-2URT44-11 5.2.1 step 6  31R4-2URT44-11 5.2.1 step 8	SK08 SKA55 SKA55 SK08 SKA02 SKA41 SKA41	•
Cutter actuator lanyard connected, safety tied, and taped? Cutter properly installed? Retaining ring properly installed? Locking cord routed correctly and tacked? Manual ripcord pin safety tied? Beacon rocker switch installed? Beacon (URT-44) rocker switch safety pin installed? Beacon set to 3-BCN (MAJCOM Option)?	14S1-11-3 para 5-7  14S1-11-3 para 7-2  14S1-11-3 para 7-2  14S1-11-3 para 8-9  14S1-11-3 para 8-9  14S1-11-3 para 8-11  31R4-2URT44-11 5.2.1 step 6  31R4-2URT44-11 5.2.1 step 5  31R4-2URT44-11 4.3 and 5.2.1	SK08 SKA55 SKA55 SK08 SKA02 SKA41 SKA41	•
Cutter actuator lanyard connected, safety tied, and taped? Cutter properly installed? Retaining ring properly installed? Locking cord routed correctly and tacked? Manual ripcord pin safety tied? Beacon rocker switch installed? Beacon (URT-44) rocker switch safety pin installed? Beacon set to 3-BCN (MAJCOM Option)? Beacon antennas properly installed?	14S1-11-3 para 5-7  14S1-11-3 para 7-2  14S1-11-3 para 7-2  14S1-11-3 para 8-9  14S1-11-3 para 8-11  31R4-2URT44-11 5.2.1 step 6  31R4-2URT44-11 5.2.1 step 5  31R4-2URT44-11 4.3 and 5.2.1 step 11; 12 and 14	SK08  SKA55 SKA55 SK08 SKA02 SKA41 SKA41 91AF0 91AF0	•
Cutter actuator lanyard connected, safety tied, and taped? Cutter properly installed? Retaining ring properly installed? Locking cord routed correctly and tacked? Manual ripcord pin safety tied? Beacon rocker switch installed? Beacon (URT-44) rocker switch safety pin installed? Beacon set to 3-BCN (MAJCOM Option)? Beacon antennas properly installed?  Beacon USB port dust cap installed?	14S1-11-3 para 5-7  14S1-11-3 para 7-2  14S1-11-3 para 7-2  14S1-11-3 para 8-9  14S1-11-3 para 8-9  14S1-11-3 para 8-11  31R4-2URT44-11 5.2.1 step 6  31R4-2URT44-11 5.2.1 step 5  31R4-2URT44-11 4.3 and 5.2.1 step 11; 12 and 14  31R4-2URT44-11	SK08  SKA55 SKA55 SK08 SKA02 SKA41 SKA41 91AF0 91AF0 SKA41	•
Cutter actuator lanyard connected, safety tied, and taped? Cutter properly installed? Retaining ring properly installed? Locking cord routed correctly and tacked? Manual ripcord pin safety tied? Beacon rocker switch installed? Beacon (URT-44) rocker switch safety pin installed? Beacon set to 3-BCN (MAJCOM Option)? Beacon antennas properly installed?  Beacon USB port dust cap installed?  ALSMS updated and one copy printed?	14S1-11-3 para 5-7  14S1-11-3 para 7-2  14S1-11-3 para 7-2  14S1-11-3 para 8-9  14S1-11-3 para 8-9  14S1-11-3 para 8-11  31R4-2URT44-11 5.2.1 step 6  31R4-2URT44-11 5.2.1 step 5  31R4-2URT44-11 4.3 and 5.2.1 step 11; 12 and 14  31R4-2URT44-11  14S1-11-3 para 8-25	SK08 SKA55 SKA55 SK08 SKA02 SKA41 SKA41 91AF0 91AF0 SKA41 SKA41	•
Cutter actuator lanyard connected, safety tied, and taped? Cutter properly installed? Retaining ring properly installed? Locking cord routed correctly and tacked? Manual ripcord pin safety tied? Beacon rocker switch installed? Beacon (URT-44) rocker switch safety pin installed? Beacon set to 3-BCN (MAJCOM Option)? Beacon antennas properly installed?  Beacon USB port dust cap installed?  ALSMS updated and one copy printed?  AFTO Form 1574 properly annotated?	14S1-11-3 para 5-7  14S1-11-3 para 7-2  14S1-11-3 para 7-2  14S1-11-3 para 8-9  14S1-11-3 para 8-11  31R4-2URT44-11 5.2.1 step 6  31R4-2URT44-11 5.2.1 step 5  31R4-2URT44-11 4.3 and 5.2.1 step 11; 12 and 14  31R4-2URT44-11  14S1-11-3 para 8-25  14S1-11-3 para 8-25	SK08  SKA55 SKA55 SK08 SKA02 SKA41 SKA41  91AF0 91AF0 SKA41 SKA99 SKA99	•

	Corrective Action:					
telek	T,O, REF.				QC BY:	Closing/Documentation EXSP BY:
	Corrective Action:					
HAM	T.O. REF:				QC BY:	Faft Hookup INSF BY:
CORRECTIVE ACTION AND REMARKS  11.  Italia	TORet	5 N	MAJOR MINOR	MAJOI A	B. QCBV:	7. Components/Container DSSP BY:
	4. INSPECTOR SHE BELOW			3. SERIAL NO.	TS	TIVITYMORKCENTER
Public reporting burden for this collection of information is estimated to average15 minutes per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Department of Defense, Washington Headquarters Services, DIOR, 1215, Jefferson Davis Highway, Suite 1204, Arington VA 22202-4302; and to OMB, Paperwork Reduction Project (0704-0188), Washington DC 20503. Please DO NOT RETURN your form to either of these addresses. Send your completed form to the Local Quality Assurance office	e time for revie his burden esti erson Davis Hig these address.	sluding th garding t 215 Jeff either of	ponse, inc mments re t, DIOR, 1	minutes per re- ution. Send co sarters Service T RETURN yo	Public reporting burden for this collection of information is estimated to average 15 minutes per response, including the time for reviewing instructions, searching exist maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this c suggestions for reducing this burden, to Department of Defense, Washington Headquarters Services, DIOR, 1215 Jefferson Davis Highway, Suite 1204, Arington VA 22 Paperwork Reduction Project (0704-0188), Washington DC 20503, Please DO NOT RETURN your form to either of these addresses. Send your completed form to	ublic reporting burden for this collectional realization and compliantaining the data needed, and compliagestions for reducing this burden, to appearance Reduction Project (0704-018)
OMB No. 0704-0188		1	1	0	Section Common to the Common C	

## Attachment 8 (Added)

# ACES II PARACHUTE (WUC PCT00) IN-PROCESS INSP. CHECKLIST

REF: T.O. 14D3-10-1	
---------------------	--

RIGGER	PARA #				
7 LEVEL	CANOPY S/N				
DATE PACKED					
IPI INIT/EMP # IP	PI STEPS				
	PRIOR TO AIRING THE CANOPY	WUC		ACES II OC	CHECKLIST
	Reference			REF: T.O.	
	SUSPENSION LINE CONTINUITY CHECK	PCT11 (Pg 3-8, Para 3-	14.2f)	PILOT CHUTE: WUC: PCT03	
	VERIFY S/N, LOT #, DOM, DOI AND P/N'S	PCT01		Serviceability of locking loop	(Pg 1-2.5, Para. 8)
	ON ALL INSTALLED TIME CHANGE PCT02				Pg 3-18.2, 9 u,v)
	ITEMS			UWARS: WUC: PCA22	g 5 10.2, 7 4, 1)
	PCT11 (Pg 1-2, Para 1-11 and 1-12)			Proper installation	(Pg 2-44.2, Para 2-52)
	ENSURE PROPER ROUTING OF REEFING LINE PCT99	(Pg 3-14, Para 3-14.5, CAUTION	1)	Proper part number 1814-017-02 and "02F")	(Pg 1-12.1, 2nd WARNING)
	REEFING LINE SPLICE AND TACKINGS			BIT test functions properly	(Pg 1-12.1, Para 1-26.12)
	AND ENSURE PROPER CORD IS USED	PCT99 (Pg 3-14,	Para 3-14.5	RISER: WUC: PCT02	,
	NOTE and Steps c, d)			Rollers for ease of operation	(Pg 1-12, Para 1-26.1)
	VERIFY CORRECTNESS OF FOUR LINE			Four-Line Jettison handle tackings	(Pg 3-12, Fig 3-8)
	JETTISON			Release pin tackings	(Pg 3-33, para 17 step o)
	PCT11 (Pg 2-22, Para 2-39.2s 1-6)			Bungee serviceability and correctness: WUC: PCT13	(Pg 3-36 Fig 3-29)
	CONTAINER INSPECTION PCT04	(Pg 1-10.2, Para 1-24.1-9)		Riser stowage tackings and connector link placement	(Pg 3-29, Para 3-14a-g, Para 3-15b, Pg 3-30, Fig 3-24, a-d)
	CLEARANCE OF AIR CHANNEL	PCT01	(Pg	LOCKING STOWS: WUC: PCT11	
3-14, Para 3-14.6j)				Proper length	(Pg 3-29, para 3-14n)
				Positioning of excess lines	(Pg 3-31, Fig 3-25, d)
	AFTER STOWING THE SUSPENSION LINES			CROSS CONNECTOR STRAP: WUC: PCT02	
	CHECK LENGTH OF LOCKING STOW	PCT11 (Pg 3-26,		Proper stowage	(Pg 3-32, Para 3-16a)
WARNING)	CARLON A ENGLISH OF STRONG	p.cm. i		Tackings	(Pg 3-32, Para 3-16b)
2.26.1.6(1)	CHECK LENGTH OF STOWS	PCT11	(Pg	CUTTERS AND PRIMARY FIRING LANYARDS: W	UC: PCT10
3-26.1, Step 1)	CHECK LENGTH OF REMAINING LINES	PCT11 (Pg 3-26.1,	oton)	Ensure cutter does not extend 1/2" above collar	(Pg 3-22, Para 3-14.12, e, NOTE)
	CHECK LENGTH OF REMAINING LINES	PCT11 (Pg 3-26.1,	step iii)	Four tackings on firing lanyards	(Pg 3-22, Para 3-14.11e-h)
	References Reviewed by TSgt Lacey, 7 Jun 11.			Tape on McMahon Snaps	(Pg 3-20, Para 3-11d)
	References Reviewed by 13gt Lacey, 7 Juli 11.			Ring installation over cutters	(Pg 3-20, Para 3-11a)
	TO: .	D 00		PITOT TUBES: WUC: PCT06	
	Discrepancies	Re QC		Cleanliness	(Pg 1-11, Para 1-24.4)
				Straightness	(Pg 1-11, Para 1-24.5)
				MORTAR TUBE: WUC: PCT08	
				Cracks and scratches	(Pg 1-11, Para 1-25.3)
				O-ring lubrication: WUC: PCT16	(Pg 1-11, Para 1-25.2)
				CONTAINER: WUC: PCT04	
				Condition of filler	(Pg 1-11, Para 1-24.3)
				Overall container condition	(Pg 1-10.2, Para 1-24)
			1	Teflon rub strips	(Pg 2-6, Para 2-15, step 1-10)
ĺ				DOCUMENTATION: WUC: PCT00	(G )
				Accuracy of 391, 392, ALSMS, IMDS 701 & 257	(General)
				1	
				QC SIGNATURE	
ĺ					

## Attachment 9 (Added)

# ACES II DROGUE(WUC: PCU00) IN-PROCESS INSP. CHECKLIST REF: T.O. 14D1-3-316

RIGGER	7 LEVEL			ACES II DROGUE QA CHECKLIST REF: T.O. 14D1-3-316			
SQUADRON	AIRCRAFT S/N_						
DATE PACKED	CANOPY S/N			OA STEPS		WUC	
IPI INIT/EMP#	IPI STEPS			REFERENCE  Ensure protective sleeve tabs on riser legs PCU06	<del></del>		
HTHVII/EMI #	WUC Reference			Ensure protective sleeve tabs on riser legs PCU06 are not between drogue severance cutters 97EAB		(Pg 4-5, Para. 4.7, WARNING)	
	ROUTING OF STATIC LINE PIN THROUGH	PCU03		Retaining door nut flush with door latch	12EBO	(Pg 4-13, al.)	
	LOOP "Y" OF DEPLOY			Right Riser leg tackings to seat structure (8/4)	PCU06	(Pg 4-13, am.)	
PCU05	(Pg 3-2, Para 3.6, Warning)			Location of Environment sensor hose	12EHB	(Pg 4-11, WARNING	
	VERIFY "S" LOOP THROUGH "R" LOOP			Before step p.)			
:	SAFETY TIE IN DISCONNECT PIN	PC	U04				
	(Pg 3-3, Para 3.6, l.)			<b>DOCUMENTATION:</b> WUC PCU00			
	ENSURE DISCONNECT PIN LANYARD IS			Accuracy of IMDS 701			
1	RIGGED WITH 12" OF SLACK	PC	U04	(General)			
	(Pg 3-10, Para 3.6, 1, p.)			OA SIGNATURE			
	VERIFY ROUTING OF TOWLINE LOCK TAB			QA SIGNATURE	_		
	THROUGH SEAT STRUCTURE LOOP ON TOP	PCU99	(Pg 4-	D.C. D.: 11 WG. J. G. 11			
·	11, Para 4.7, n, warning) INSERT TIELINE LOOP THROUGH STATIC			References Reviewed by TSgt Lacey, 7 Jun 11.			
1	LINE LOOP, SAFETY TIE (WAXED FF NYLON)	PCU99	(Pg				
4.12, I	Para 4.7, t.)						

#### REMOVED ITEMS

Old item	P/N #	S/N	DOM	DOI	DOE
Canopy					

## Attachment 10 (Added)

 $\begin{tabular}{ll} Table A10.1. & (Added) Life Preserver and Inspection and Component Record \ . \end{tabular}$ 

	1	Life Preserve	r and Inspec	ction and C	Component	Record		
Туре			Part #		Stock#			
	LPU-38/P		0115200-1			4220-01-510-8555		
			Container	· Informati	ion			
Part #			Serial #			DOM	DOI	
		Li	fe Preserver	Cell Infor	mation	1	1	<u> </u>
Part # 115230-	1		L-Inner Cell S	erial #		DOM	DOI	
Part # 115240-1			R-Outer Cell Serial #			DOM	DOI	
113240-1	•		Inflat	tor (Left)		l		
Туре		Serial #		Lot #		DOM	DOI	DOE
			Inflate	or (Right)		l		
Type		Serial #		Lot #		DOM	DOI	DOE
			Batte	ry (Left)				
Type		MFG		Lot #		DOM	DOI	DOE
			Batter	ry (Right)				
Type		MFG		Lot #		DOM	DOI	DOE
			Inspect	ion Record	l			
Due	Date	Type of	Inspected	I.P.I. #	I.P.I. #			Q.C. By
Inspection	Inspected	Inspection	By	1	2			Q.C. By
		hnical Order			T.C.T.O			
T.0	0.	Date	Change #	Date	TC	ГО #	Date C/W	Initials
14S-1-102-31		1 Nov 03						
11P10-6-7		13 Jan 04						
		In P	rocess Inspe	ctions for 1	LPU-38/P			
1	<ul> <li>Battery service</li> <li>Bladder information</li> </ul>	,	14P10-6-7) WU ncil/Serial #) W	JC: LPJ40 UC: LPL11		VUC: LPJ10		
2	- Inflator o-rings installed properly (CO2/Bottom gasket) (TO 14S-1-102-31Para 6.2.2) WUC: LPJ10 - Battery voltage test (TO 11P10-6-7) WUC: LPJ40 - Assembly of Inflatable Assemblies Into Inflation Shell Assy, (TO 14S-1-102-31Para 6.2.1) WUC: LPL11							

	(TO 14S-1-102-31Para 6.4) WUC: LPL11	
QC	Ensure all packing aids are accounted for (zipper slider/keep straps) (14S-1-102-31)     Chest strap buckles and collar adapter assembly properly installed (14S-1-102-31)     Records updating AFTO Form 466B & computer generated forms (14S-1-102-31)	WUC: LPL00 WUC: LPL03, LPL06 WUC: LPL00